

Fig. 1








	Fig. 4 Due period & period	T2 1/4再期 T3 1/4再期 T4] [1/4·T] [1/4·T]	t4 t5 t6 t7 t8	$0 \rightarrow 1 1 \rightarrow 1 1 \rightarrow 0 0 \rightarrow 0 0 \rightarrow 0 0 \rightarrow 0 0 \rightarrow 0$	$0 \rightarrow 0 \mid 0 \rightarrow 0 \mid 0 \rightarrow 0 \mid 0 \rightarrow 0 \mid 1 \rightarrow 1 \mid 1 \rightarrow 0 \mid 0 \rightarrow 0$	$0 \to 0$ $0 \to 0$ $0 \to 1$ $1 \to 1$ $1 \to 0$ $0 \to 0$ $0 \to 0$.	$1 \rightarrow 0 0 \rightarrow 1 1 \rightarrow 1$
	the pariod	T_1		1 → 1	0 0 ← 0 0	0 0 ← 0 0	0 0 0 0 0
Q11, Q14 (Q21, Q24) Q12, Q13 (Q22, Q23) Q15, Q18 (Q25, Q28) Q16, Q17		1/4	t1				$\overline{}$

Wote what current changes from 0 to 1 p.u. 世: 0→1 indicates that it is maintained at current of 1 p.u. 1→1 indicates that it is maintained at current of 1 p.u. 1→0 indicates that current changes from 1 p.u. to 0.

